Maryland Historical Trust

Maryland Inventory of Historic Properties number: CH 494 Name: MD6 Over Zahiah Luo	MP			
The bridge referenced herein was inventoried by the Maryland Sta Historic Bridge Inventory, and SHA provided the Trust with eligib. The Trust accepted the Historic Bridge Inventory on April 3, 2001 determination of eligibility.	oility determinations in February 2001.			
MARYLAND HISTORICAL TRUST Eligibility Recommended Eligibility Not RecommendedX				
Criteria:ABCD Considerations:A Comments:	_BCDEFGNone			
Comments				
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001			

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

SHA Bridge No. 8006 Bridge name MD 6 over Zekiah Swamp
LOCATION: Street/Road name and number MD 6 (Charles Street)
City/town Newtown Vicinity X
County Charles
This bridge projects over: Road Railway Water X Land
Ownership: State X County _ Municipal _ Other _
HISTORIC STATUS: Is bridge located within a designated historic district? Yes No _X National Register-listed district National Register-determined-eligible district Name of district Name of district
BRIDGE TYPE: Timber Bridge : Beam Bridge Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge
Metal Truss Bridge
Movable Bridge : Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder Rolled Girder Concrete Encased Plate Girder Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X : Concrete Arch X Concrete Slab Concrete Beam Rigid Frame
Other Type Name

DESCRIPTION:

Describe Setting

Bridge No. 8006 carries MD 6 over Zekiah Swamp in Charles County. MD 6 runs in a generally east-west direction over the southern flowing Zekiah Swamp. The bridge is located in a rural, undeveloped region. The bridge carries two lanes of traffic in opposing directions and is located between Newton and Dentsville.

Describe Superstructure and Substructure:

Bridge No. 8006 is a hybrid structure consisting of the original pre-1929 west abutment of a masonry bridge, and 1929 single-span filled concrete arch bridge, and a 1967 steel beam structure which was added to widen the bridge. The original concrete arch is oriented on a 90-degree skew, and is 67 feet long with a 42-foot clear arch span. It carried a 24 foot roadway section with gravel surfacing, earth fill, and had a pierced concrete parapets with coping and no curbs, and solid inscribed concrete endposts. The side faces of the bridge had an inscribed arch section. The masonry portions of the former bridge, including a pier and the east abutment, were used as riprap for the present bridge.

The current bridge was widened by 20 feet 6 inches, and presently carries a 44-foot clear roadway. The length of the steel beam bridge is 70 feet 8 inches. The span length is 67 feet. The widened section has pedestal type abutments on piles and a brush curb type parapets with one aluminum bridge railing. When the arch bridge was widened, the north parapet was eliminated and the south parapet was replaced with an identical curb with railing. The reinforced concrete deck is topped with a bituminous wearing surface.

An inspection report from 1995 lists this bridge as being in good condition with a sufficiency rating of 84.9. The bituminous wearing surface is rutting and cracking. There is light spalling, cracking, and scaling on the arch, and the steel beams have moderate rust.

Discuss Major Alterations:

The bridge was widened in 1967, incorporating a steel beam bridge section with the concrete arch. In 1994, repairs were made to the longitudinal joint between the original bridge section and the widened portion.

HISTORY:

WHEN was bridge built (ac	ctual date or date range)	<u>1929, 1967</u>
This date is: Actual	Estimated	
Source of date: Plaque	Design plans	County bridge files/inspection form X
Other (specify)		
WHY was bridge built? W	idening and geometric improve	ment to MD 6 between LaPlata and New Market
WHO was the designer? Sta		
WHO was the builder? Stat		
WHY was bridge altered?	To widen the bridge to meet ap	proach roadway section
Ų.	organized bridge-building ca	-
	part of the improvements to MI	
A - Events B	onal Register significance for i - Person	ts association with:
C- Engineering/ar	chitectural character	

This bridge does not have National Register significance due to its widening with a steel beam section.

CH-494

Was bridge constructed in response to significant events in Maryland or local history?

No, the improvement of Charles County roads was the result of several events that occurred during the first 3 decades of the twentieth century. The original Good Roads movement was aimed toward improving the primary routes such as MD 6 throughout the state, as well as connecting roads between counties. A later impact of this program included geometric improvement of secondary routes and the reconstruction of substandard bridges. With the rapid increases in the technology of motorized vehicles, many functionally substandard bridges were replaced with stronger modern structures. During the 1930 the State Roads Commission focused on the improvement of safety and comfort for the motorist on the main routes throughout the state, but also improved secondary roads and the farm-to-market network of feeder roads. By the 1930s, bridges that were once adequate when initial reconstruction began were also being replaced.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth & development of the area?

No, during the time period when this bridge was built, Charles County was not experiencing a great degree of growth. Charles County remained a rural, agricultural region, with its roads mainly serving tourists passing through the late-twentieth century.

Is the bridge located in an area that may be eligible for historic designation?

No, this bridge is not located in an area that is eligible for historic designation.

Is the bridge a significant example of its type?

No, the bridge is not a significant example of its type. The addition of a steel beam bridge section and the replacement of the original parapets compromise the integrity of the bridge.

Does bridge retain integrity of important elements described in Context Addendum?

No, the bridge no longer has its original parapets, and the addition of the steel beam section detracts from the integrity of the structure.

Is bridge a significant example of work of manufacturer, designer and/or engineer?

No, the bridge is not a significant work of a manufacturer, designer, or engineer.

Should bridge be given further study before significance analysis is made?

No, this bridge should not be given further study.

BIBLIOGRAPHY:

County inspection/bridge files	SHA inspection/bridge files _	X
Other (list):		

Johnson, Arthur Newhall

1899 The Present Condition of Maryland Highways. In *Report on the Highways of Maryland*. Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.

P.A.C. Spero & Company and Louis Berger & Associates

Historic Highway Bridges in Maryland: 1631-1960: Historic Context Report. Maryland State Highway Administration, Maryland State Department of Transportation, Baltimore, Maryland.

State Roads Commission


1958 A History of Road Building in Maryland. State Roads Commission of Maryland, Baltimore, Maryland.

CH-494

Tyrrell, H. Grattan 1909 Concrete Concrete Bridges and Culverts for Both Railroads and Highways. The Myron C. Clark Publishing Company, Chicago and New York.

SURVEYOR:

ate bridge recorded December 1997
ame of surveyor Wallace, Montgomery & Associates / P.A.C. Spero & Company
rganization/Address P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204
none number (410) 296-1635 FAX number (410) 296-1670





1. CH-494
2. MD6 over Zekiah Swamp
3. Charles Co., MD
4. Wallace, Montgomery & Assoc.
5. 12/97
6. MD SHPO

7. Elevation looking upstream

8 10+4



1 CH-494 2, MD 6 over Zekiah Swamp 3. Charles Co. MD Wallace, Montgomery & Assoc. 5. 12/97 6 MD SHPO Elevation looking downstream

8. 20F4

4



· Sa 3. Cuperes County 6. MD SHPO T. ROADWAY LOOKING FAST



1, CH-494 2. MD 6 over Zekiah Swamp 3, Charles Co., MD 4. Wallace, Montgomery & Assoc. 5. 12/97 6, MD SHPO 7. Looking West 8, 4 of 4